CONSTRUCTION EQUIPMENT A12512 GEN ASPHALT VOLVO ECR235E 314290 - REAR RIGHTEINA

Sample No:VCP439199Oil Type:MOBIL MOBILUBE HD 80W90Job No:A12512 GEN ASPHALT

VOLVO

SAMPLE INFORMATION VCP439199 Sample Number VCP278609 Sample Date 21 Apr 2024 05 Oct 2020 Machine Hours 2515 730 Oil Hours 1000 730 Oil Changed Changed Changed NORMAL NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 310 166 CONTAMINATION Water % NEG NEG Silicon 12 ppm 49 Sodium **||** <1 0 ppm Potassium ppm 5 $\square 2$ WEAR METALS

Iron	ppm	215	128	
Copper	ppm	1	 <1	
Lead	ppm	 <1	 <1	
Tin	ppm		<1	
Aluminum	ppm	12	0	
Chromium	ppm	5	2	
Molybdenum	ppm	1	1	
Nickel	ppm		0	
Titanium	ppm	2	<1	
Silver	ppm	0	<1	
Manganese	ppm	3	3	
Vanadium	ppm	<1	0	

ADDITIVES Calcium 34 61 ppm 2 Magnesium 6 ppm 34 Zinc ppm 18 Phosphorus 979 440 ppm Barium ppm 3 4 4 Boron 178 ppm



HOFFMAN EQUIPMENT - LIONVILLE

120 GORDON DRIVE LIONVILLE, PA US 19341 Contact: JIM FEHR jim.fehr@hoffmanequip.com T: (610)363-9200 F: (610)594-0829

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO8879

 Unique No:
 11002508

 Signed:
 Sean Felton

 Report Date:
 30 Apr 2024


 Contact/Location:
 JIM FEHR - VOLVO8879

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Contact/Location: JIM FEHR - VOLVO8879