

# **CONSTRUCTION EQUIPMENT**

VOLVO L90H 627047 - DIESEL EXHAUST FLUID (DEF)

Sample No: VCP430531

Oil Type: **DEF** (Diesel Exaust Fluid)

Job No: 6895HR

SAMPLE INFORMATION					
_	AF UNITA I TUN				
Sample Number		VCP430531			
Sample Date		22 Apr 2024			
Machine Hours		6895			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		SEVERE			
CONTAMINATION					
LUNTAMIN	IATION				
Hydrocarbon	scalar	<b>■</b> NONE			
DEE COMPLETION					
DEF CONDITION					
Urea Content	%	<b>27.3</b>			
Density @ 20°C	g/cm3	<b>1.0869</b>			
Refracting Index		<b>1.3743</b>			
Appearance	scalar	<b>■Clear &amp; Bright</b>			



### **HIGHWAY EQUIPMENT & SUPPLY CO MAIN**

PO BOX 1957 HARRISBURG, PA US 17105

Contact: BRANDON MIDDAUGH bmiddaugh@hwyequip.com

T:

F: (717)564-3568

## Diagnosis

We advise that you check for the source of coolant. Recommend drain diesel exhaust fluid (def) if not already done and flush before refilling with diesel exhaust fluid (def). There is a high concentration of coolant present in the diesel exhaust fluid (def). Urea content is abnormal. The diesel exhaust fluid (def) is no longer serviceable due to the presence of contaminants.

Depot: VOLVO0025 **Unique No:** 11002584 Signed: Doug Bogart Report Date: 13 May 2024




# **CONSTRUCTION EQUIPMENT**





#### GRAPHS





Report Id: VOLVO0025 [WUSCAR] 06161865 (Generated: 05/14/2024 04:11:02) Rev: 1