



# CONSTRUCTION EQUIPMENT

## VOLVO EC480EL 311198 - COOLANT



**Sample No:** VCP0007891

**Oil Type:** {unknown}

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP0007891	---	---	---
Sample Date	24 Apr 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY**

8750 PHILIPS HWY  
JACKSONVILLE, FL  
US 32256

Contact: TECHNICIAN ACCOUNT  
catherine.anastasio@wearcheck.com

T:  
F: (904)737-1260



### COOLANT CONDITION

pH	Scale 0-14	■ 7.74	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.2	---	---	---
Freezing Point	°C	■ -33	---	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



### CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0092  
**Unique No:** 11002596  
**Signed:** Jonathan Hester  
**Report Date:** 01 May 2024

Submitted By: TECHNICIAN ACCOUNT




# CONSTRUCTION EQUIPMENT




## VOLVO GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

