

## CONSTRUCTION EQUIPMENT 700822 VOLVO L150H 6885 - COOLANT



Sample No: VCP443784

Oil Type: VOLVO COOLANT VCS (YELLOW)

**Job No:** 700822

SAMPLE IN	NFORMATION				
Sample Number	•	VCP443784			
Sample Date		17 Apr 2024			
Machine Hours		6075			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	<b>7.18</b>			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■ NT			
Percentage Glycol	%	<b>50.1</b>			
Freezing Point	°C	<b>-35</b>			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Yllow			



ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL
NEW HUDSON, MI
US 48165
Contact: PAUL ELZERMAN
paul.elzerman@altaequipment.com
T: (248)356-5200
F: (248)356-2029

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO2990Unique No:11002599Signed:Jonathan HesterReport Date:01 May 2024



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

