



CONSTRUCTION EQUIPMENT

12923 VOLVO L25H SD11572 - FRONT AXLE



Sample No: VCE167225
Oil Type: GEAR OIL SAE 80W90
Job No: 12923



SAMPLE INFORMATION

Sample Number	VCE167225	---	---	---
Sample Date	23 Apr 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

TRANSOURCE TRUCK & EQUIPMENT

901 EAST 60TH STREET NORTH
 SIOUX FALLS, SD
 US 57104

Contact: BRAD MAUPIN
 brad.maupin@transourceusa.com

T:
 F: (605)336-2248



OIL CONDITION

Visc @ 40°C	cSt	█ 63.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 20	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 254	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 5	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 12	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3546	---	---	---
Magnesium	ppm	█ 3	---	---	---
Zinc	ppm	█ 1412	---	---	---
Phosphorus	ppm	█ 1119	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 127	---	---	---

Depot: VOLVO0035
Unique No: 11002873
Signed: Sean Felton
Report Date: 30 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

