

CONSTRUCTION EQUIPMENT X59526 TADANO GR550XL-3 542269 - REAR AXLE



Sample No: VCP438269

Oil Type: GEAR OIL SAE 80W90

Job No: X59526

| VOLVO | | | | | |
|---------------|-------------|---------------|--|--|--|
| SAMPLE | INFORMATION | | | | |
| Sample Number | | VCP438269 | | | |
| Sample Date | | 25 Apr 2024 | | | |
| Machine Hours | | 843 | | | |
| Oil Hours | | 0 | | | |
| Oil Changed | | Changed | | | |
| Sample Status | | NORMAL | | | |
| | | | | | |
| OIL CONDITION | | | | | |
| Visc @ 40°C | cSt | 190 | | | |
| VOLVO | | | | | |
| CONTAMINATION | | | | | |
| Water | % | NEG | | | |
| Silicon | | | | | |
| Sodium | ppm | ■12 | | | |
| | ppm | 2 | | | |
| Potassium | ppm | □ 1 | | | |
| VOLVO | | | | | |
| WEAR METALS | | | | | |
| Iron | ppm | 17 | | | |
| Copper | ppm | ■8 | | | |
| Lead | ppm | ■<1 | | | |
| Tin | ppm | | | | |
| Aluminum | ppm | 1 | | | |
| Chromium | ppm | ■<1 | | | |
| Molybdenum | ppm | ■<1 | | | |
| Nickel | ppm | ■<1 | | | |
| Titanium | ppm | <1 | | | |
| Silver | ppm | 0 | | | |
| Manganese | ppm | ■ <1 | | | |
| Vanadium | ppm | <1 | | | |
| VOLVO | | | | | |
| ADDITIVE | 2 | | | | |
| Calcium | ppm | ■80 | | | |
| Magnesium | ppm | 1 | | | |
| Zinc | ppm | ■30 | | | |
| Phosphorus | ppm | 1256 | | | |
| Barium | ppm | ■ 3 | | | |
| Boron | ppm | 246 | | | |



SCOTT EQUIPMENT COMPANY LLC - Saint Rose
PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DENISE CORVERS
dcorvers@scottcompanies.com
T: (504)461-0961
F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SCOSAI
Unique No: 11004041
Signed: Wes Davis
Report Date: 30 Apr 2024

Contact/Location: DENISE CORVERS - SCOSAI



CONSTRUCTION EQUIPMENT





