

CONSTRUCTION EQUIPMENT X18542 IAA VOLVO L90H 625476 - FRONT AXLE



Sample No: VCP438306

Oil Type: VOLVO WB 102

Job No: X18542 IAA

SAMPLE	INFORMATION			
Sample Number		VCP438306	VCE67882D	
Sample Date		25 Apr 2024	07 Aug 2023	
Machine Hours		3966	3022	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	42.3	41.6	
VOLVO	UNIA TION			
LUNIAN	IINATION			
Water	%	NEG	NEG	
Silicon	ppm	12	1 2	
Sodium	ppm	■2	6	
Potassium	ppm	■ 0	2	
WEAR M	IETALS			
Iron	ppm	□ 33	■ 108	
Copper	ppm	4	13	
Lead	ppm	0	<u></u> <1	
Tin	ppm	- <1	0	
Aluminum	ppm	0	<u> </u>	
Chromium	ppm	<u> </u>	3	
Molybdenum	ppm	2	6	
Nickel	ppm	■0	- <1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	■ 3	7	
Vanadium	ppm	0	0	
ADDITIV	IES			
Calcium	ppm	■3883	■3957	
Magnesium	ppm	12	12	
Zinc	ppm	■ 1571	1606	
Phosphorus	ppm	■1334	1328	
Barium	ppm	0	0	
D	C P	= 100		



SCOTT EQUIPMENT COMPANY LLC - Jackson

3860 I-55 South JACKSON, MS US 39212

Contact: DWIGHT MCDOUGAL DMCDOUGAL@SCOTTCOMPANIES.COM

T:

F: (601)326-3359

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8771Unique No:11004059Signed:Wes DavisReport Date:30 Apr 2024

126

Boron



CONSTRUCTION EQUIPMENT





GRAPHS

