



CONSTRUCTION EQUIPMENT

G08558 VOLVO L260H 1254 - COOLANT



Sample No: VCP437245
Oil Type: {unknown}
Job No: G08558



SAMPLE INFORMATION

Sample Number	VCP437245	---	---	---
Sample Date	23 Apr 2024	---	---	---
Machine Hours	6642	---	---	---
Sample Status	NORMAL	---	---	---

HOFFMAN EQUIPMENT - DEPTFORD
 1330 HURFFVILLE ROAD
 DEPTFORD, NJ
 US 08096
 Contact: TAMMY SANDORA
 tammy.sandora@hoffmanequip.com
 T: (856)227-6400
 F: (856)227-0046



COOLANT CONDITION

pH	Scale 0-14	■ 7.35	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 43.9	---	---	---
Freezing Point	°C	■ -19	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO8880
Unique No: 11004164
Signed: Jonathan Hester
Report Date: 02 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

