



CONSTRUCTION EQUIPMENT

527088-10 VOLVO L150G 22536 - COOLANT



Sample No: VCP428578
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 527088-10



SAMPLE INFORMATION

Sample Number	VCP428578	VCP432740	---	---
Sample Date	17 Apr 2024	26 Aug 2023	---	---
Machine Hours	17290	16482	---	---
Sample Status	NORMAL	NORMAL	---	---

MR BULTS INC
 SULLIVAN COUNTY LANDFILL
 MONTICELLO, NY
 US 12701
 Contact:

T: (208)324-7148
 F:



COOLANT CONDITION

pH	Scale 0-14	8.29	7.68	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	0	---	---
Percentage Glycol	%	52.5	69.7	---	---
Freezing Point	°C	-40	-66	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	---	---
Coolant Color	Yllow	Orange	---	---

Depot: MRBMONNY
Unique No: 11004166
Signed: Jonathan Hester
Report Date: 02 May 2024

Contact/Location: ? ? - MRBMONNY



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

