



CONSTRUCTION EQUIPMENT

702925 VOLVO L220H 3368 - REAR AXLE



Sample No: VCP451096
Oil Type: VOLVO WB 102
Job No: 702925



SAMPLE INFORMATION

Sample Number	VCP451096	VCP445980	VCP432374	VCP425445
Sample Date	24 Apr 2024	14 Feb 2024	12 Dec 2023	18 Jul 2023
Machine Hours	5581	5101	4672	3780
Oil Hours	0	0	0	0
Oil Changed	Not Chngd	Changed	Not Chngd	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

BLUE GOOSE GROWERS
 16059 W ORANGE AVE
 FT PIERCE, FL
 US 34945
 Contact: SERVICE MANAGER



OIL CONDITION

Visc @ 40°C	cSt	43.9	43.2	44.6	47.6
-------------	-----	-------------	------	------	------

T: (772)461-3020
 F:



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	13	11	10	12
Sodium	ppm	1	1	2	4
Potassium	ppm	0	0	0	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	59	31	46	83
Copper	ppm	4	15	8	42
Lead	ppm	<1	<1	0	0
Tin	ppm	0	<1	0	0
Aluminum	ppm	<1	<1	<1	2
Chromium	ppm	<1	<1	<1	2
Molybdenum	ppm	<1	1	0	2
Nickel	ppm	0	0	0	0
Titanium	ppm	0	<1	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	<1	3
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	3770	3482	3532	4052
Magnesium	ppm	27	16	16	24
Zinc	ppm	1495	1545	1503	1679
Phosphorus	ppm	1283	1276	1254	1386
Barium	ppm	0	0	0	0
Boron	ppm	112	113	125	130

Depot: BLUFOR
Unique No: 11005588
Signed: Wes Davis
Report Date: 01 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

