

 Sample No:
 VCP454715

 Oil Type:
 VOLVO WB 102

 Job No:
 702804 ALTA RENTS

	INFORMATIO	N		
			 -	_
Sample Number		VCP454715	 	
Sample Date		24 Apr 2024	 	
Machine Hours		1555	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO				
V OIL CON	DITION			
Visc @ 40°C	cSt	42.8	 	
	AINATION			
Water	%	NEG	 	
Silicon	ppm	1 3	 	
Sodium	ppm	■4	 	
Potassium	ppm	2	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	2	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	 <1	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	0	 	
	••			
	/ES		 	
Calcium	ppm	3610	 	
Magnesium	ppm	1 1	 	
Zinc	ppm	1398	 	
-	P.P. ***			



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. The copper level is abnormal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0096

 Unique No:
 11005598

 Signed:
 Jonathan Hester

 Report Date:
 03 May 2024

 Contact/Location: Robert LaPlante - VOLVO0096

1217

0 🔲

105

Phosphorus

Barium

Boron

ppm

ppm


ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Page 2 of 2