

## CONSTRUCTION EQUIPMENT 25457 VOLVO A45 353393 - REAR AXLE



Sample No: VCP422216

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 25457

Sample Number  Sample Date  VCP422216   Sample Date  24 Apr 2024	 
Sample Number         VCP422216            Sample Date         24 Apr 2024	 
Sample Date 24 Apr 2024	
·	
Machine Hours 3956	 
Machine Hours	
Oil Changed	 
Sample Status NORMAL	 
VOLVO	
OIL CONDITION	
Visc @ 40°C	 
VOLVO	
CONTAMINATION	
Water % <b>NEG</b>	 
Silicon ppm 2	 
Sodium ppm <b>3</b>	 
Potassium ppm <b>5</b>	 
VOLVO	
WEAR METALS	
Iron ppm <b>■288</b>	 
Copper ppm 2	 
<b>Lead</b> ppm <b>■0</b>	 
Tin ppm <b>■0</b>	 
Aluminum ppm <b>©</b>	 
Chromium ppm <b>3</b>	 
Molybdenum ppm <b>2</b>	 
Nickel ppm <b>0</b>	 
Titanium ppm <b>0</b>	 
Silver ppm 0	 
Manganese ppm <b>T</b>	 
Vanadium ppm <b>0</b>	 
VOLVO	
ADDITIVES	
Calcium ppm <b>155</b>	
Calcium         ppm         155            Magnesium         ppm         2	 
Magnesium ppm <b>□2</b>	
Magnesium         ppm         ■2            Zinc         ppm         ■67	 

**218 - ASCENDUM MACHINERY INC - N. CHARLESTON** 7235 CROSS COUNTRY RD.

NORTH CHARLESTON, SC US 29418

Contact: MATT MITCHAM

matt.mitcham@ascendummachinery.com

1:

F: (843)414-1129

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:11005605Signed:Wes DavisReport Date:01 May 2024



## **CONSTRUCTION EQUIPMENT**





