

CONSTRUCTION EQUIPMENT VOLVO L90H 05625448 - COOLANT



Sample No: VCP436479

Oil Type: HYBRID (HOAT) COOLANT

Job No:

SAMPLE IN	FORMATION			
Sample Number	-	VCP436479	VCP437123	
Sample Date		24 Apr 2024	23 Jan 2024	
Machine Hours		0	0	
Sample Status		NORMAL	NORMAL	
COOLANT	CONDITION			
рН	Scale 0-14	7.86	7.61	
Reserve Alkalinity	Scale 0-20			
Nitrites	ppm	■ NT	■NT	
Percentage Glycol	%	■ 51.7	51.0	
Freezing Point	°C	□ -38	□ -38	
CONTAMIN	IATION			
Coolant Appearance	-	normal	normal	
Coolant Color		Yllow	Yllow	



CITY CARTING

221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS tavins@citycart.net
T: (203)223-3885
F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:CITMILCONUnique No:11005807Signed:Jonathan HesterReport Date:03 May 2024



CONSTRUCTION EQUIPMENT





GRAPHS

