

CONSTRUCTION EQUIPMENT 6895HR VOLVO L90H 627047 - COOLANT



Sample No: VCP371040

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: 6895HR

SAMPLE IN	FORMATION				
Sample Number	-	VCP371040			
Sample Date		23 Apr 2024			
Machine Hours		470			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	■8.21			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■ NT			
Percentage Glycol	%	48.9			
Freezing Point	°C	□ -31			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Yllow			



HIGHWAY EQUIPMENT & SUPPLY CO MAIN

PO BOX 1957
HARRISBURG, PA
US 17105
Contact: BRANDO

Contact: BRANDON MIDDAUGH bmiddaugh@hwyequip.com

1:

F: (717)564-3568

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO0025Unique No:11005808Signed:Jonathan HesterReport Date:03 May 2024



CONSTRUCTION EQUIPMENT





