

CONSTRUCTION EQUIPMENT VOLVO L220H 3569 - REAR AXLE



Sample No: VCP441752

Oil Type: MOBIL MOBILGARD 424

Job No:

VOLVO	INFORMATION			
	INFURMATION			
Sample Number		VCP441752	VCP440846	
Sample Date		24 Apr 2024	01 Feb 2024	
Machine Hours		2000	968	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CON	NITION			
			- 44 - 7	
Visc @ 40°C	cSt	51.6	41.7	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	■17	14	
Sodium	ppm	■0	1 2	
Potassium	ppm	2	0	
Totassium	ррш			
VOLVO				
WEAR N	METALS			
Iron	ppm	47	6 1	
Copper	ppm	-<1	0	
Lead	ppm	0	0	
Tin	ppm	■0	0	
Aluminum	ppm	2	< 1	
Chromium	ppm	1	2	
Molybdenum	ppm	6	3	
Nickel	ppm	■0	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	2	5	
Vanadium	ppm	0	0	
VOLVO	IEC			
ADDITIV	LEZ			
Calcium	ppm	■3818	■3885	
Magnesium	ppm	■50	1 4	
Zinc	ppm	1600	■1584	
Phosphorus	ppm	1371	1336	
Barium	ppm	0	0	
Boron	ppm	153	127	



ARNOLD MACHINERY COMPANY 464 WASHINGTON STREET S TWIN FALLS, ID US 83301 Contact: JANAE HYMAS jhymas@arnoldmachinery.com T: (208)733-1715

Diagnosis

F: (775)356-7152

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO1835Unique No:11006778Signed:Wes DavisReport Date:02 May 2024



CONSTRUCTION EQUIPMENT





