CONSTRUCTION EQUIPMENT 703060 - FRONT AXLE

 Sample No:
 VCP455425

 Oil Type:
 VOLVO WB 102

 Job No:
 703060

VOLVO

SAMPLE INFORMATION VCP455425 Sample Number Sample Date 25 Apr 2024 Machine Hours 19901 Oil Hours 2000 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 66.16 CONTAMINATION Water % NEG Silicon ppm 5 Sodium 0 🔲 ppm Potassium ppm 0 WEAR METALS Iron ppm 19 Copper ppm 0 Lead ppm 0 🔲 Tin ppm **||** <1 Aluminum ppm ■<1 Chromium **||** <1 ppm Molybdenum ppm **<**1 Nickel 0 ppm Titanium 0 ppm Silver 0 ppm Manganese ppm <1

Vanadium

ppm

0

01 **ADDITIVES** Calcium 2210 ppm Magnesium 26 ppm 1018 Zinc ppm Phosphorus 820 ppm Barium 0 🔲 ppm Boron 21 ppm



FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE DETROIT, MI US 48207 Contact: KEITH HALL keith.hall@fpt1.com T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:FERDETUnique No:11007255Signed:Jonathan HesterReport Date:10 May 2024Contact/Location:KEITH HALL - FERDET

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

