



# CONSTRUCTION EQUIPMENT

703459 VOLVO A30G 753488 - BOGIE/CENTER AXLE



**Sample No:** VCP451327  
**Oil Type:** {unknown}  
**Job No:** 703459



## SAMPLE INFORMATION

Sample Number	VCP451327	---	---	---
Sample Date	29 Apr 2024	---	---	---
Machine Hours	668	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
9601 BOGGY CREEK RD  
ORLANDO, FL  
US 32824  
Contact: Robert LaPlante  
robert.laplante@altg.com  
T: (407)508-9736  
F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	■ 88.1	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 10	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 3	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 530	---	---	---
Copper	ppm	■ 20	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 1	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ 9	---	---	---
Molybdenum	ppm	4	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	15	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	962	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	388	---	---	---
Phosphorus	ppm	1424	---	---	---
Barium	ppm	1	---	---	---
Boron	ppm	287	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 11008035  
**Signed:** Wes Davis  
**Report Date:** 03 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

