



CONSTRUCTION EQUIPMENT

703206 FRITZ SENNEBOGEN 835C 2743 - COOLANT



Sample No: VCP444517
Oil Type: FLEETGUARD ES COMPLEAT
Job No: 703206 FRITZ



SAMPLE INFORMATION

Sample Number	VCP444517	---	---	---
Sample Date	29 Apr 2024	---	---	---
Machine Hours	10751	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY - METRO WEST
 56195 PONTIAC TRAIL
 NEW HUDSON, MI
 US 48165
 Contact: PAUL CONZ
 paul.conz@altg.com
 T: (313)348-8861
 F: (248)356-2029



COOLANT CONDITION

pH	Scale 0-14	■ 8.21	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 600	---	---	---
Percentage Glycol	%	■ 54.0	---	---	---
Freezing Point	°C	■ -45	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO2990
Unique No: 11008118
Signed: Jonathan Hester
Report Date: 07 May 2024




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

