

CONSTRUCTION EQUIPMENT VOLVO A45G 32890 - DIESEL ENGINE



Sample No: VCP424270

Oil Type: DIESEL ENGINE OIL SAE 40

Job No:

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP424270	 	
Sample Date		13 Mar 2024	 	
Machine Hours		2359	 	
Oil Hours		503	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	12.6	 	
Base Number (BN)		8.3	 	
Oxidation (PA)	%	51	 	
	,,	• •		
VOLVO	IATION			
CONTAMIN	-			
Water	%	NEG	 	
Soot %	%	■ 0.2	 	
Nitration (PA)	%	57	 	
Sulfation (PA)	%	49	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	4	 	
Sodium	ppm	2	 	
Potassium	ppm	■ 0	 	
VOLVO				
WEAR ME	TALS			
Iron	ppm	16	 	
Copper	ppm	■8	 	
Lead	ppm	■ 0	 	
Tin	ppm	2	 	
Aluminum	ppm	■3	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	■ 55	 	
Nickel	ppm	<u> </u>	 	
Titanium	ppm		 	
Silver	ppm	■0	 	
Manganese	ppm		 	
Vanadium	ppm	<1	 	
VOLVO	_			
ADDITIVE:	2			
Calcium	ppm	1181	 	
Magnesium	ppm	■817	 	
Zinc	ppm	1175	 	
Phosphorus	ppm	1000	 	
Barium	ppm	■ 0	 	
Boron	ppm	2	 	



GLOVER CONSTRUCTION CO. INC.

4493 US HWY 301 N
PLEASANT HILL, NC
US 27866
Contact: BRENDA GAY
bgay@gloverconstruction.com
T:
F: (252)536-5078

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Valve wear is indicated. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:GLOPLEUnique No:11008811Signed:Jonathan HesterReport Date:06 May 2024

Contact/Location: BRENDA GAY - GLOPLE



CONSTRUCTION EQUIPMENT





