



CONSTRUCTION EQUIPMENT

VOLVO A40G 352026 - REAR AXLE



Sample No: VCP440655
Oil Type: MOBIL MOBILUBE HD PLUS 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP440655	VCP436364	VCP395130	VCP402956
Sample Date	15 Apr 2024	08 Feb 2024	30 Oct 2023	29 Aug 2023
Machine Hours	10378	9959	9458	9029
Oil Hours	920	501	929	500
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	130	130	137	138
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	9	2	2
Sodium	ppm	0	0	0	<1
Potassium	ppm	1	2	0	<1

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	8	10	7	7
Copper	ppm	<1	<1	0	0
Lead	ppm	<1	0	0	0
Tin	ppm	<1	0	0	0
Aluminum	ppm	2	2	0	0
Chromium	ppm	<1	0	0	<1
Molybdenum	ppm	3	4	0	1
Nickel	ppm	<1	0	0	0
Titanium	ppm	<1	<1	0	0
Silver	ppm	<1	0	0	0
Manganese	ppm	<1	0	0	0
Vanadium	ppm	<1	0	0	0



ADDITIVES

Calcium	ppm	479	683	192	231
Magnesium	ppm	19	28	17	18
Zinc	ppm	177	249	111	88
Phosphorus	ppm	1026	1514	956	1021
Barium	ppm	0	12	2	0
Boron	ppm	189	239	178	221

Depot: SCHGRE
Unique No: 11009496
Signed: Wes Davis
Report Date: 06 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

