



CONSTRUCTION EQUIPMENT

VOLVO A40G 342373 - REAR AXLE



Sample No: VCP442846
Oil Type: MOBIL MOBILUBE HD PLUS 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP442846	VCP399415	VCP341871	VCP402952
Sample Date	15 Apr 2024	12 Mar 2024	09 Oct 2023	29 Aug 2023
Machine Hours	12958	12715	11957	11645
Oil Hours	1001	758	995	683
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	136	137	132	133
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	6	12	3
Sodium	ppm	0	<1	0	0
Potassium	ppm	1	1	2	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	10	11	23	13
Copper	ppm	1	2	<1	0
Lead	ppm	<1	<1	0	0
Tin	ppm	<1	<1	0	0
Aluminum	ppm	2	2	2	0
Chromium	ppm	<1	<1	<1	<1
Molybdenum	ppm	2	2	1	<1
Nickel	ppm	<1	<1	0	0
Titanium	ppm	<1	<1	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	0	0
Vanadium	ppm	<1	<1	0	0



ADDITIVES

Calcium	ppm	271	306	438	432
Magnesium	ppm	11	12	10	10
Zinc	ppm	109	126	148	145
Phosphorus	ppm	1012	953	976	1009
Barium	ppm	0	0	0	0
Boron	ppm	208	170	173	198

Depot: SCHGRE
Unique No: 11009502
Signed: Wes Davis
Report Date: 06 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

