

Sample No: VCP417964

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

**Job No:** SPM702852

CVMDIE	E INFORMATION	η		
	. INFUNIATION		,	
Sample Number		VCP417964		 
Sample Date		01 May 2024		 
Machine Hours		19728		 
Oil Hours		0		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>54.2</b>		 
VISC @ 40 C	CSt	<b>34.2</b>		 
VOLVO				
CONTAN	MINATION			
Water	%	NEG		 
Silicon	ppm	■20		 
Sodium	ppm	<b>2</b>		 
Potassium	ppm	2		 
rotassium	ррпп			
VOLVO				
WEAR N	<b>NETALS</b>			
Iron	ppm	<b>69</b>		 
Copper	ppm	<b>3</b>		 
Lead	ppm	<b>-</b> <1		 
Tin	ppm	_ <1		 
Aluminum	ppm	<b>2</b>		 
Chromium	ppm	 <b>■</b> <1		 
Molybdenum	ppm	<b>1</b> <1		 
Nickel	ppm	■<1		 
Titanium		<1		 
	ppm	· -		
Silver	ppm	0		 
Manganese	ppm	<b>-</b> <1		 
Vanadium	ppm	0		 
VOLVO				 
ADDITIV	VES			
Calcium	ppm	<b>4169</b>		 
Magnesium	ppm	<b>19</b>		 
Zinc	ppm	<b>1636</b>		 
Phosphorus	ppm	■ 1347		 
Barium	ppm	<b>■</b> 0		 
Boron		■157		 
DOIOII	ppm	<b>1</b> 37		 



U-PULL-AND-PAY LLC - WEST PALM BEACH 551 BENOIST FARMS ROAD WEST PALM BEACH, FL US 33411 Contact: DAVID OZIMEK david.ozimek@upullandpay.com T: (561)846-1597 F: (561)793-2449

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:UPUWESUnique No:11017789Signed:Wes DavisReport Date:08 May 2024



## **CONSTRUCTION EQUIPMENT**





