



# CONSTRUCTION EQUIPMENT

TUCKER PAVING VOLVO A25G 752497 - DIESEL ENGINE



**Sample No:** VCP440654  
**Oil Type:** VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3  
**Job No:** TUCKER PAVING



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



## SAMPLE INFORMATION

Sample Number	VCP440654	---	---	---
Sample Date	13 Feb 2024	---	---	---
Machine Hours	2768	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 100°C	cSt	█ 12.5	---	---	---
Base Number (BN)	mg KOH/g	█ 9.5	---	---	---
Oxidation (PA)	%	65	---	---	---



## CONTAMINATION

Water	%	NEG	---	---	---
Soot %	%	█ 0.4	---	---	---
Nitration (PA)	%	66	---	---	---
Sulfation (PA)	%	55	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---



## WEAR METALS

Iron	ppm	█ 11	---	---	---
Copper	ppm	█ 3	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 56	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 1381	---	---	---
Magnesium	ppm	846	---	---	---
Zinc	ppm	█ 1283	---	---	---
Phosphorus	ppm	█ 1081	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 11	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

**Depot:** VOLVO0093  
**Unique No:** 11018413  
**Signed:** Wes Davis  
**Report Date:** 09 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

