

CONSTRUCTION EQUIPMENT 687813 VOLVO A30G 752847 - BOGIE/CENTER AXLE



Sample No: VCP437946

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 687813

VOLVO SAMPLE	INFORMATION				
	. IINI UNINA I IUI		VCD202520	VCD204057	
Sample Number		VCP437946	VCP392529	VCP384957	
Sample Date		16 Mar 2024	15 Mar 2023	15 Nov 2022	
Machine Hours		3292	1063	484	
Oil Hours		2792	500	500	
Oil Changed		Not Changd	Not Changd	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	204	206	87.5	
	CSC			07.5	
VOLVO					
CONTAN	MINATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	4	6	6	
Sodium	ppm	■ 0	< 1	- <1	
Potassium	ppm	2	 <1	3	
VOLVO	AFTALC				
WEAR M	IETALS				
Iron	ppm	174	141	■ 377	
Copper	ppm	10	6	1 7	
Lead	ppm	0	□0		
Tin	ppm	■<1	0	- <1	
Aluminum	ppm	■<1	< 1	- <1	
Chromium	ppm	2	_2	7	
Molybdenum	ppm	7	■8	1 2	
Nickel	ppm	■<1	- <1	4	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■ 4	5	1 2	
Vanadium	ppm	0	0	0	
VOLVO	IFC				
ADDITIV	FZ				
Calcium	ppm	■379	391	1 030	
Magnesium	ppm	16	2 3	4	
Zinc	ppm	184	188	424	
Phosphorus	ppm	1068	1 092	□ 1250	
Barium	ppm	2	0	0	
Boron	ppm	174	190	230	



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services

PMServices@ripaconstruction.com

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:11018975Signed:Wes DavisReport Date:09 May 2024

Contact/Location: PM Services ? - RIPTAM



CONSTRUCTION EQUIPMENT





