



CONSTRUCTION EQUIPMENT

VOLVO A40G 342658 - BOGIE/CENTER AXLE



Sample No: VCP447446
Oil Type: MOBIL MOBILUBE HD 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP447446	VCP416944	VCP331547	VCP404645
Sample Date	29 Apr 2024	13 Feb 2024	06 Nov 2023	24 Aug 2023
Machine Hours	10764	10200	9682	9142
Oil Hours	1082	518	1056	516
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	139	139	138	138
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	4	1	2
Sodium	ppm	0	<1	<1	<1
Potassium	ppm	1	<1	0	<1

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	45	10	11	8
Copper	ppm	<1	<1	0	0
Lead	ppm	<1	<1	0	0
Tin	ppm	<1	<1	0	0
Aluminum	ppm	<1	1	0	0
Chromium	ppm	<1	0	0	0
Molybdenum	ppm	2	1	1	1
Nickel	ppm	<1	<1	0	0
Titanium	ppm	<1	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	1	<1	0	0
Vanadium	ppm	<1	0	0	0



ADDITIVES

Calcium	ppm	197	200	187	201
Magnesium	ppm	12	13	14	18
Zinc	ppm	87	86	92	78
Phosphorus	ppm	970	958	1024	1002
Barium	ppm	0	0	0	0
Boron	ppm	196	173	171	220

Depot: SCHGRE
Unique No: 11019009
Signed: Wes Davis
Report Date: 09 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

