

CONSTRUCTION EQUIPMENT

59558 VOLVO EC300ELR 317660 - REAR RIGHT FINAL DRIVE

Sample No: VCP437017

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: X59558

CVMDIE	INFORMATIO	1		
	INFURMATIU			
Sample Number		VCP437017	 	
Sample Date		02 May 2024	 	
Machine Hours		1020	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	276	 	
VOLVO	IIN A TION			
LONTAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	<u> </u>	 	
Sodium	ppm	5	 	
Potassium	ppm	13	 	
WEAR M	IFTAI C			
_				
Iron	ppm	■393	 	
Copper	ppm	2	 	
Lead	ppm	1	 	
Tin	ppm	- <1	 	
Aluminum	ppm	26	 	
Chromium	ppm	10	 	
Molybdenum	ppm	2	 	
Nickel	ppm	■2	 	
Titanium	ppm	2	 	
Silver	ppm	0	 	
Manganese	ppm	6	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIV	ES			
Calcium	ppm	10	 	
Magnesium	ppm	4	 	
Zinc	ppm	2 1	 	
Phosphorus	ppm	■834	 	
Barium	ppm	■0	 	
Boron	ppm	131	 	
501011	ppiii			

SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DANA FOSHEE
dfoshee@scottcompanies.com
T: (504)461-0961
F: (504)461-0970

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Metal levels are typical for a new component breaking in. Elemental level of silicon (Si) above normal indicating ingress of seal material. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:11019024Signed:Don BaldridgeReport Date:10 May 2024

Contact/Location: DANA FOSHEE - SCOSAI



CONSTRUCTION EQUIPMENT





