



# CONSTRUCTION EQUIPMENT

714276 RENTALS VOLVO L90 627190 - FRONT AXLE



**Sample No:** VCP451326  
**Oil Type:** VOLVO WET BRAKE TRANSAXLE OIL  
**Job No:** 714276 RENTALS



## SAMPLE INFORMATION

Sample Number	VCP451326	---	---	---
Sample Date	07 May 2024	---	---	---
Machine Hours	575	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
9601 BOGGY CREEK RD  
ORLANDO, FL  
US 32824  
Contact: Robert LaPlante  
robert.laplante@altg.com  
T: (407)508-9736  
F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█41.7	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█19	---	---	---
Sodium	ppm	█0	---	---	---
Potassium	ppm	█4	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█45	---	---	---
Copper	ppm	█2	---	---	---
Lead	ppm	█1	---	---	---
Tin	ppm	█<1	---	---	---
Aluminum	ppm	█1	---	---	---
Chromium	ppm	█3	---	---	---
Molybdenum	ppm	█15	---	---	---
Nickel	ppm	█1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█10	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█3998	---	---	---
Magnesium	ppm	█12	---	---	---
Zinc	ppm	█1603	---	---	---
Phosphorus	ppm	█1305	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█155	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 11019036  
**Signed:** Wes Davis  
**Report Date:** 09 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

