

CONSTRUCTION EQUIPMENT VOLVO L60H 62 1074 - TRANSMISSION (AUTO)



TARA

Sample No: VCP443669

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Oil Type: Job No:

SAMPLE INFORMATION						
Sample Number		VCP443669				
Sample Date		06 May 2024				SCOTT EQUIPMENT COMPANY LLC - Jackson
Machine Hours		8110				3860 I-55 South
Oil Hours		0				JACKSON, MS
Oil Changed		Changed				US 39212
Sample Status		NORMAL				Contact: DWIGHT MCDOUGAL
						DMCDOUGAL@SCOTTCOMPANIES.COM
VOLVO						T:
OIL CON			<u>-</u>	-	<u>.</u>	F: (601)326-3359
Visc @ 40°C	cSt	27.4				
VOLVO						Diagnosis
	MINATION	Resample at the next service interval to monitor.All component wear rates				
Water	% NEG					
Silicon	ppm	3				are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable
Sodium	ppm	1				
Potassium	ppm	2				
Totassian	ppiii	2				for the time in service.
VOLVO						
WEAR I	METALS					
Iron	ppm	9				-
Copper	ppm	3				
Lead	ppm	0				
Tin	ppm					
Aluminum	ppm	2				
Chromium	ppm	 <1				
Molybdenum	ppm	 <1				
Nickel	ppm	0				
Titanium	ppm	<1				
Silver	ppm	0				
Manganese	ppm	 <1				
Vanadium	ppm	<1				
						_
ADDITI	VES					
Calcium	ppm	96				-
Magnesium	ppm	3				
Zinc	ppm	24				
Phosphorus	ppm	192				
Barium	ppm	0				
Boron	ppm	94				

 Depot:
 VOLV08771

 Unique No:
 11020486

 Signed:
 Wes Davis

 Report Date:
 10 May 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

