

CONSTRUCTION EQUIPMENT VOLVO L20H 1220520 - HYDRAULIC SYSTEM



Sample No: VCP451162

Oil Type: AW HYDRAULIC OIL ISO 68

Job No:

SAMPLE II	NFORMATION				
Sample Number		VCP451162			
Sample Date		08 May 2024			
Machine Hours		423			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
				-	
Visc @ 40°C	cSt	68.7			
Acid Number (AN)	mg KOH/g	0.46			
CONTAMINATION					
Water	%	NEG			
Particles >4µm	70	3730			
Particles >6µm		■ 197			
Particles > 14µm		17			
ISO 4406:1999 (c)		19/15/11			
Silicon	ppm	■3			
Sodium	ppm	■0			
Potassium	ppm	2			
T Otassiani	PPIII				
VOLVO					
WEAR ME	IALS				
Iron	ppm	■3			
Copper	ppm	4			
Lead	ppm	1			
Tin	ppm	■<1			
Aluminum	ppm	■2			
Chromium	ppm	■ <1			
Molybdenum	ppm				
Nickel	ppm	■0			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	<1			
VOLVO					
ADDITION					
Calcium	ppm	213			
Magnesium	ppm	5			
Zinc	ppm	487			
Phosphorus	ppm	■390			
Barium	ppm	■0			
Boron	ppm	2			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 68. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0093Unique No:11021453Signed:Wes DavisReport Date:13 May 2024



CONSTRUCTION EQUIPMENT





GRAPHS

