

# CONSTRUCTION EQUIPMENT AMERICAN EAGLE VOLVO L 150H 7255 - REAR AXLE



Sample No: VCP395787

Oil Type: VOLVO WB 102

Job No: AMERICAN EAGLE

VOLVO				
SAMPLE	INFORMATIO	N		
Sample Number	-	VCP395787	 	
Sample Date		01 May 2024	 	
Machine Hours		2015	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>43.4</b>	 	
VOLVO	IINA TION			
LUNIAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	<b>■</b> 13	 	
Sodium	ppm	■0	 	
Potassium	ppm	<b>■</b> 5	 	
WEAR M	IETALS			
Iron	ppm	<b>112</b>	 	
Copper	ррт	<b>2</b>	 	
Lead	ppm	<b>■</b> <1	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>3</b>	 	
Molybdenum	ppm	<b>3</b>	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■4	 	
Vanadium	ppm	<1	 	
Variadium	ppiii	` '		
VOLVO				
<b>ADDITIV</b>	EZ			
Calcium	ppm	<b>4071</b>	 	
Magnesium	ppm	<b>11</b>	 	
Zinc	ppm	<b>1656</b>	 	
Phosphorus	ppm	<b>1395</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>153</b>	 	



## **ARNOLD MACHINERY COMPANY** 4136 NORTH DONOVAN WAY LAS VEGAS, NV

US 89030 Contact: TONY SHAW tshaw@arnoldmachinery.com T: (702)642-9000 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO5856Unique No:11021925Signed:Wes DavisReport Date:13 May 2024

Contact/Location: TONY SHAW - VOLVO5856



### **CONSTRUCTION EQUIPMENT**





