



CONSTRUCTION EQUIPMENT

SW1033701 VOLVO A30G 742497 - REAR AXLE



Sample No: VCP359734
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: SW1033701



SAMPLE INFORMATION

Sample Number	VCP359734	---	---	---
Sample Date	02 May 2024	---	---	---
Machine Hours	4845	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ARNOLD MACHINERY COMPANY
 4136 NORTH DONOVAN WAY
 LAS VEGAS, NV
 US 89030
 Contact: TONY SHAW
 tshaw@arnoldmachinery.com
 T: (702)642-9000
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 152	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 24	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 3	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 126	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 12	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 2523	---	---	---
Magnesium	ppm	█ 48	---	---	---
Zinc	ppm	█ 876	---	---	---
Phosphorus	ppm	█ 1028	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 62	---	---	---

Depot: VOLVO5856
Unique No: 11021927
Signed: Sean Felton
Report Date: 14 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

