



CONSTRUCTION EQUIPMENT

SWO-071810 APAC VOLVO L150G 23140 - REAR RIGHT FINAL DRIVE



Sample No: VCP449755
Oil Type: {unknown}
Job No: SWO-071810 APAC



SAMPLE INFORMATION

Sample Number	VCP449755	---	---	---
Sample Date	07 May 2024	---	---	---
Machine Hours	6814	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

MIDSOUTH PAVING INC

750 CLOW RD
BIRMINGHAM, AL
US 35217

Contact: CHRIS MCCOY
chmccoy@apac.com
T: (205)365-3448
F: (205)808-5431



OIL CONDITION

Visc @ 40°C	cSt	■ 54.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 18	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 2	---	---	---



WEAR METALS

Iron	ppm	■ 17	---	---	---
Copper	ppm	■ <1	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	17	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	3242	---	---	---
Magnesium	ppm	82	---	---	---
Zinc	ppm	1326	---	---	---
Phosphorus	ppm	1098	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	134	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: APABIR
Unique No: 11021953
Signed: Wes Davis
Report Date: 14 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

