



CONSTRUCTION EQUIPMENT

SPM702435 SENNEBOGEN 830ME 830.0.2822 - REAR AXLE



Sample No: VCP446178
Oil Type: TDTO FLUID SAE 50
Job No: SPM702435



SAMPLE INFORMATION

Sample Number	VCP446178	---	---	---
Sample Date	23 Apr 2024	---	---	---
Machine Hours	9464	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT CO - ORLAND PARK
5000 INDUSTRIAL HWY
GARY, IN
US 46406
Contact: DAVE ENG
DAVE.ENG@ALTG.COM
T: (312)350-2560
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 66.9	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 16	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 65	---	---	---
Copper	ppm	█ 10	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 2778	---	---	---
Magnesium	ppm	█ 8	---	---	---
Zinc	ppm	█ 1144	---	---	---
Phosphorus	ppm	█ 1020	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 90	---	---	---

Depot: VOLVO8885
Unique No: 11030493
Signed: Sean Felton
Report Date: 16 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

