

CONSTRUCTION EQUIPMENT
SPM702435 AMG SENNEBOGEN 830ME 830.0.2822 - FRONT RIGHT FINA

Sample No: VCP446186

Oil Type: **GEAR OIL SAE 80W90** 

Job No: SPM702435 AMG

VOLVO					
SAMPLE	INFORMATION				
Sample Number	-	VCP446186			
Sample Date		23 Apr 2024			
Machine Hours		9464			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		ATTENTION			
OIL CONDITION					
Visc @ 40°C	cSt	<b>102</b>			
VISC @ 40 C	CSt	102			
VOLVO					
CONTAMINATION					
Water	%	NEG			
Silicon	ppm	■8			
Sodium	ppm	<b>10</b>			
Potassium	ppm	<b>■</b> <1			
WEAR METALS					
_					
Iron	ppm	<b>92</b>			
Copper	ppm	<b>■ 17</b>			
Lead	ppm	<b>■</b> <1			
Tin	ppm	<b>■&lt;1</b>			
Aluminum	ppm	<b>■&lt;1</b>			
Chromium	ppm	<b>□</b> <1			
Molybdenum	ppm	<b>0</b>			
Nickel	ppm	■0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>2</b>			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	3				
Calcium	ppm	<b>1362</b>			
Magnesium	ppm	<b>6</b>			
Zinc	ppm	<b>■568</b>			
Phosphorus	ppm	<b>698</b>			
Barium	ppm	<b>■&lt;1</b>			
Boron	ppm	<b>48</b>			



**ALTA EQUIPMENT CO - ORLAND PARK** 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal.

Depot: VOLVO8885 **Unique No:** 11030513 Signed: Don Baldridge Report Date: 16 May 2024



## **CONSTRUCTION EQUIPMENT**





