



# CONSTRUCTION EQUIPMENT

SPM702435 AMG SENNEBOGEN 830ME 830.0.2822 - REAR LEFT FINAL DRIVE



**Sample No:** VCP446179  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM702435 AMG



## SAMPLE INFORMATION

Sample Number	VCP446179	---	---	---
Sample Date	23 Apr 2024	---	---	---
Machine Hours	9464	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
5000 INDUSTRIAL HWY  
GARY, IN  
US 46406  
Contact: DAVE ENG  
DAVE.ENG@ALTG.COM  
T: (312)350-2560  
F:



## OIL CONDITION

Visc @ 40°C	cSt	● 67.1	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 8	---	---	---
Sodium	ppm	■ 14	---	---	---
Potassium	ppm	■ <1	---	---	---



## WEAR METALS

Iron	ppm	■ 55	---	---	---
Copper	ppm	■ 9	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 2	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	● 2535	---	---	---
Magnesium	ppm	■ 9	---	---	---
Zinc	ppm	● 1092	---	---	---
Phosphorus	ppm	■ 969	---	---	---
Barium	ppm	■ <1	---	---	---
Boron	ppm	■ 104	---	---	---

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

**Depot:** VOLVO8885  
**Unique No:** 11030514  
**Signed:** Don Baldrige  
**Report Date:** 16 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

