

CONSTRUCTION EQUIPMENT E15335 PONSSE A130490W - SWING DRIVE



Sample No: VCP405976

Oil Type: PONSSE 75W90

Job No: E15335

VOLVO CAMPIF	INFORMATION				
Sample Number	INI ONIMATION	VCP405976	VCP416689	VCP395225	
Sample Date		10 May 2024	10 May 2023	16 Feb 2023	
Machine Hours		5953	1423	252	
Oil Hours		0	0	252	
Oil Changed		Changed	Changed	Changed	
Sample Status		SEVERE	ABNORMAL	ABNORMAL	
VOLVO					
OIL CONE	DITION				
Visc @ 40°C	cSt	153	1 01	130	
CONTAM	INATION				
		<u>.</u>			
Water	%	NEG	NEG	NEG	
Silicon	ppm	13	■3	- <1	
Sodium	ppm	■<1	■0	□0	
Potassium	ppm	■ 6	1	□ 0	
VOLVO					
WEAR M	ETALS				
Iron	ppm	246	■82	■13	
Copper	ppm	1170	<u>^</u> 258	5 5	
Lead	ppm	^ 66	1 3	6	
Tin	ppm	4 93	<u>^</u> 23	4	
Aluminum	ppm	2	0	- <1	
Chromium	ppm	2	- <1	■ 0	
Molybdenum	ppm	0	< 1	0	
Nickel	ppm	2	- <1	□ 0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	3	 < 1	<1	
Vanadium	ppm	0	0	0	
ADDITIV	ES				
Calcium	ppm	141	35	20	
Magnesium	ppm	0	2	7	
Zinc	ppm	297	□ 60	26	
Phosphorus	ppm	1206	1133	281	
Barium	ppm	0	0	0	
_					

■309



JON LOZIER

14 SUNNYFIELD DRIVE
FORT KENT, ME
US 04743

Contact: JON LOZIER

T: (207)436-0366 F:

Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:JONFORMEUnique No:11031752Signed:Don BaldridgeReport Date:17 May 2024

ppm

368

Boron



CONSTRUCTION EQUIPMENT





