



# CONSTRUCTION EQUIPMENT

W0230543 VOLVO L260H 1353 - FRONT AXLE



**Sample No:** VCP429420  
**Oil Type:** CHEVRON 1000 THF  
**Job No:** W0230543



## SAMPLE INFORMATION

Sample Number	VCP429420	---	---	---
Sample Date	08 May 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	3991	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC**  
 1350 NE LOOP 820  
 FORT WORTH, TX  
 US 76106  
 Contact: ROB HOLCOMB  
 rholcomb@romco.com  
 T: (817)798-9289  
 F: (817)626-8983



## OIL CONDITION

Visc @ 40°C	cSt	█ 51.0	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 78	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 2834	---	---	---
Magnesium	ppm	█ 16	---	---	---
Zinc	ppm	█ 1201	---	---	---
Phosphorus	ppm	█ 1007	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 17	---	---	---

**Depot:** VOLVO0081  
**Unique No:** 11031772  
**Signed:** Wes Davis  
**Report Date:** 16 May 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

