



CONSTRUCTION EQUIPMENT

W0230543 VOLVO L260H 1353 - TRANSMISSION (AUTO)



Sample No: VCP428505
Oil Type: DEXRON III
Job No: W0230543



SAMPLE INFORMATION

Sample Number	VCP428505	---	---	---
Sample Date	08 May 2024	---	---	---
Machine Hours	3994	---	---	---
Oil Hours	3994	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ROMCO INC
1350 NE LOOP 820
FORT WORTH, TX
US 76106
Contact: CHRIS BITNER
CBitner@romco.com
T:
F: (817)626-8983



OIL CONDITION

Visc @ 40°C	cSt	█ 28.1	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 64	---	---	---
Copper	ppm	█ 30	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 111	---	---	---
Magnesium	ppm	█ 8	---	---	---
Zinc	ppm	█ 51	---	---	---
Phosphorus	ppm	█ 183	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 57	---	---	---

Depot: VOLVO0081
Unique No: 11031879
Signed: Wes Davis
Report Date: 16 May 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

