



# CONSTRUCTION EQUIPMENT

## X48160 VOLVO ECR88D 219164 - REAR LEFT FINAL DRIVE



**Sample No:** VCP452466  
**Oil Type:** VOLVO API GL-5 SAE 75W90  
**Job No:** X48160



### SAMPLE INFORMATION

Sample Number	<b>VCP452466</b>	VCP430450	---	---
Sample Date	<b>09 May 2024</b>	28 Feb 2024	---	---
Machine Hours	<b>983</b>	780	---	---
Oil Hours	<b>0</b>	780	---	---
Oil Changed	<b>Changed</b>	Changed	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
 PO BOX 997  
 SAINT ROSE, LA  
 US 70087  
 Contact: DENISE CORVERS  
 dcorvers@scottcompanies.com  
 T: (504)461-0961  
 F: (504)461-0970



### OIL CONDITION

Visc @ 40°C	cSt	<b>167</b>	168	---	---
-------------	-----	------------	-----	-----	-----



### CONTAMINATION

Water	%	<b>NEG</b>	NEG	---	---
Silicon	ppm	<b>4</b>	4	---	---
Sodium	ppm	<b>4</b>	3	---	---
Potassium	ppm	<b>&lt;1</b>	2	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	<b>319</b>	292	---	---
Copper	ppm	<b>3</b>	1	---	---
Lead	ppm	<b>0</b>	<1	---	---
Tin	ppm	<b>&lt;1</b>	0	---	---
Aluminum	ppm	<b>&lt;1</b>	2	---	---
Chromium	ppm	<b>4</b>	5	---	---
Molybdenum	ppm	<b>2</b>	2	---	---
Nickel	ppm	<b>0</b>	<1	---	---
Titanium	ppm	<b>0</b>	<1	---	---
Silver	ppm	<b>0</b>	0	---	---
Manganese	ppm	<b>5</b>	4	---	---
Vanadium	ppm	<b>0</b>	0	---	---



### ADDITIVES

Calcium	ppm	<b>17</b>	0	---	---
Magnesium	ppm	<b>0</b>	1	---	---
Zinc	ppm	<b>39</b>	42	---	---
Phosphorus	ppm	<b>297</b>	314	---	---
Barium	ppm	<b>0</b>	2	---	---
Boron	ppm	<b>0</b>	0	---	---

**Depot:** SCOSAI  
**Unique No:** 11034513  
**Signed:** Don Baldrige  
**Report Date:** 21 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

