



CONSTRUCTION EQUIPMENT

714988 SENNEBOGEN 840 2345 - REAR AXLE



Sample No: VCP454470
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: 714988



SAMPLE INFORMATION

Sample Number	VCP454470	VCP421770	---	---
Sample Date	14 May 2024	03 Apr 2023	---	---
Machine Hours	3005	1029	---	---
Oil Hours	1000	1029	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE
 DETROIT, MI
 US 48207

Contact: KEITH HALL
 keith.hall@fpt1.com

T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 139	█ 185	---	---
-------------	-----	-------	-------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	█ <1	█ 2	---	---
Sodium	ppm	█ 2	█ 2	---	---
Potassium	ppm	█ 5	█ 0	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 5	█ 16	---	---
Copper	ppm	█ 3	█ 7	---	---
Lead	ppm	█ 0	█ 0	---	---
Tin	ppm	█ 0	█ 0	---	---
Aluminum	ppm	█ 0	█ <1	---	---
Chromium	ppm	█ 0	█ 0	---	---
Molybdenum	ppm	█ 0	█ 0	---	---
Nickel	ppm	█ 0	█ 0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	█ <1	█ <1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	█ 0	█ 11	---	---
Magnesium	ppm	█ 0	█ 3	---	---
Zinc	ppm	█ 0	█ 0	---	---
Phosphorus	ppm	█ 860	█ 1023	---	---
Barium	ppm	█ 0	█ 330	---	---
Boron	ppm	█ 58	█ <1	---	---

Depot: FERDET
Unique No: 11034528
Signed: Angela Borella
Report Date: 21 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

