

CONSTRUCTION EQUIPMENT X18599 GA PACIFIC VOLVO L110H 632051 - FRONT AXLE



Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

Job No: X18599 GA PACIFIC

VOLVO		NI		
SAMPLI	E INFORMATIO	N		
Sample Number	-	VCP438309	VCE043873	
Sample Date		09 May 2024	09 May 2024	
Machine Hours		9796	9796	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	
VOLVO	DITION			
OIL CON	DITIUN			
Visc @ 40°C	cSt	■ 58.0	■ 57.4	
COLVO	MINATION			
		NE C	NEC	
Water	%	NEG	NEG	
Silicon	ppm	10	9	
Sodium	ppm	■<1	- <1	
Potassium	ppm	■ 0	0	
WEAR	AFTAI S			
_		= 40	= 10	
Iron	ppm	19	1 9	
Copper	ppm	□ <1	= <1	
Lead	ppm	0	0	
Tin	ppm	■<1	- <1	
Aluminum	ppm	■ <1	0	
Chromium	ppm	0	0	
Molybdenum	ppm		- <1	
Nickel	ppm	■0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	1	1	
Vanadium	ppm	0	0	
ADDITIV	VES			
Calcium	ppm	■3459	□3496	
Magnesium	ppm	0	0	
Zinc	ppm	1281	■1296	
Phosphorus	ppm	1150	1136	
Barium	ppm	0	0	
Boron	ppm	16	19	
DOTOTT	ppiii	10	13	



SCOTT EQUIPMENT COMPANY LLC - Jackson

3860 I-55 South JACKSON, MS US 39212

Contact: DWIGHT MCDOUGAL DMCDOUGAL@SCOTTCOMPANIES.COM

T:

F: (601)326-3359

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. High concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8771 **Unique No:** 11034539 Signed: Angela Borella Report Date: 21 May 2024



CONSTRUCTION EQUIPMENT





GRAPHS

