



# CONSTRUCTION EQUIPMENT

12645 OLD CASTLE VOLVO L120H 633359 - TRANSMISSION (AUTO)



**Sample No:** VCP453562  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 12645 OLD CASTLE



## SAMPLE INFORMATION

Sample Number	VCP453562	---	---	---
Sample Date	09 May 2024	---	---	---
Machine Hours	3864	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

### HOFFMAN EQUIPMENT - LIONVILLE

120 GORDON DRIVE

LIONVILLE, PA

US 19341

Contact: JIM FEHR

jim.fehr@hoffmanequip.com

T: (610)363-9200

F: (610)594-0829



## OIL CONDITION

Visc @ 40°C	cSt	■ 30.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 3	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 15	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 3	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ 2	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	■ 330	---	---	---
Magnesium	ppm	■ 6	---	---	---
Zinc	ppm	138	---	---	---
Phosphorus	ppm	■ 306	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 105	---	---	---

**Depot:** VOLVO8879

**Unique No:** 11034574

**Signed:** Wes Davis

**Report Date:** 20 May 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

