



CONSTRUCTION EQUIPMENT

VOLVO L150H 6989 - COOLANT



Sample No: VCP436466
Oil Type: VOLVO 50/50
Job No:



SAMPLE INFORMATION

Sample Number	VCP436466	VCP432776	VCP407072	---
Sample Date	09 May 2024	22 Feb 2024	15 Dec 2023	---
Machine Hours	7072	6479	5961	---
Sample Status	NORMAL	SEVERE	NORMAL	---

CITY CARTING

221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:



COOLANT CONDITION

pH	Scale 0-14	7.11	7.25	7.19	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	NT	---
Percentage Glycol	%	47.0	46.8	46.5	---
Freezing Point	°C	-28	-26	-26	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	▲ oil	normal	---
Coolant Color	Yllow	Red	Yllow	---

Depot: CITMILCON
Unique No: 11034598
Signed: Jonathan Hester
Report Date: 22 May 2024




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

