



# CONSTRUCTION EQUIPMENT

G08784 OCLF VOLVO A30G 742095 - COOLANT



**Sample No:** VCP435239  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** G08784 OCLF



## SAMPLE INFORMATION

Sample Number	VCP435239	---	---	---
Sample Date	13 May 2024	---	---	---
Machine Hours	11692	---	---	---
Sample Status	NORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	█ 6.82	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	█ NT	---	---	---
Percentage Glycol	%	█ 54.1	---	---	---
Freezing Point	°C	█ -45	---	---	---



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**HOFFMAN EQUIPMENT - DEPTFORD**  
 1330 HURFFVILLE ROAD  
 DEPTFORD, NJ  
 US 08096  
 Contact: TAMMY SANDORA  
 tammy.sandora@hoffmanequip.com  
 T: (856)227-6400  
 F: (856)227-0046

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VOLVO8880  
**Unique No:** 11034599  
**Signed:** Jonathan Hester  
**Report Date:** 22 May 2024




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

