

CONSTRUCTION EQUIPMENT VOLVO L60H 621848 - REAR AXLE



Sample No: VCP449525
Oil Type: VOLVO WB 101

Job No:

SAMPLI	E INFORMATION			
Sample Number		VCP449525	VCP421429	
Sample Date		14 May 2024	18 Aug 2023	
Machine Hours		5769	4546	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
Sample Status		HORWAL	NONVIAL	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	43.8	■39.6	
CUNTAI	MINATION			
_				
Water	%	NEG	NEG	
Silicon	ppm	16	1 7	
Sodium	ppm	■8	■8	
Potassium	ppm	■2	- <1	
VOLVO				
WEAR N	METALS			
Iron	ppm	□87	□ 313	
Copper	ppm	6	24	
Lead	ppm	0	0	
Tin	ppm	0	2	
Aluminum	ppm	1	□ <1	
Chromium	ppm	2	7	
Molybdenum	ppm	2	5	
Nickel	ppm	0	1	
Titanium	ppm	0	<1	
Silver	ppm	<1	0	
Manganese	ppm	3	1 2	
Vanadium	ppm	<1	<1	
variacium	ррпп	NI NI		
VOLVO				
ADDITIV	VEZ.			
Calcium	ppm	■3963	■4050	
Magnesium	ppm	■ 9	■10	
Zinc	ppm	■1567	■1637	
Phosphorus	ppm	1309	□1329	
Barium	ppm	0	0	
Boron	ppm	123	1 39	



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

|. _ ._ _ .

F: (239)481-3302

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:11035991Signed:Wes DavisReport Date:21 May 2024



CONSTRUCTION EQUIPMENT





