

# CONSTRUCTION EQUIPMENT 716461 BRIAR VOLVO A25 752384 - FRONT AXLE



Sample No: VCP454522

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 716461 BRIAR

VOLVO SAMPLE	INFORMATIO	N		
	. IMI OMPIATIO		 	
Sample Number		VCP454522	 	
Sample Date		16 May 2024	 	
Machine Hours		3018	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
OIL CON	DITION			
Visc @ 40°C	cSt	85.3	 	
	CSI	05.5	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>5</b>	 	
	ρριτι		 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>417</b>	 	
Copper	ppm	<b>■</b> 58	 	
Lead	ppm	<b>-&lt;1</b>	 	
Tin	ppm	2	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>6</b>	 	
Molybdenum	ppm	<b>12</b>	 	
Nickel		<b>6</b>	 	
Titanium	ppm	0		
	ppm			
Silver	ppm	<1	 	
Manganese	ppm	■14	 	
Vanadium	ppm	<1	 	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	■826	 	
Magnesium	ppm	■0	 	
Zinc	ppm	■362	 	
Phosphorus		1430	 	
Barium	ppm	<b>1430</b>	 	
	ppm	_		
Boron	ppm	■237	 	



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

tlark@altaequipfl.com T:

F: (239)481-3302

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

 Depot:
 VOLVO0090

 Unique No:
 11036028

 Signed:
 Sean Felton

 Report Date:
 22 May 2024



## **CONSTRUCTION EQUIPMENT**





