

CONSTRUCTION EQUIPMENT

SW-33848-2 MAVERICK VOLVO EC480E 315097 - RIGHT SWING DE

Sample No: VCP369670

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: SW-33848-2 MAVERICK

VOLVO					
SAMPL	E INFORMATION				
Sample Number		VCP369670	VCP443488	VCP422954	
Sample Date		10 May 2024	02 Nov 2023	31 Jul 2023	
Machine Hours		2422	1250	679	
Oil Hours		1200	600	679	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	ABNORMAL	
VOITAGE UII LUN	IDITION				
Visc @ 40°C	cSt	=126	m 102	m 172	
VISC @ 40°C	CST	126	183	172	
VOLVO					
CONTAI	MINATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■ 5	1 0	1 4	
Sodium	ppm	1	1	0	
Potassium	ppm	2	0	2	
WEAR	METALS				
Iron	ppm	113	■ 417	□ 116	
Copper	ppm	6	1 16	<u>▲</u> 68	
Lead	ppm	0	0	□ <1	
Tin	ppm	■0	0	0	
Aluminum	ppm	■<1	= <1	1 2	
Chromium	ppm	2	1 5	2	
Molybdenum	ppm	51	2 19	□ < 1 □	
Nickel	ppm	■0	0	= <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	1	4	5	
Vanadium	ppm	<1	0	0	

90

1

60

732

1

41

55

< 1</p>

62

□319

4

0



ARNOLD MACHINERY COMPANY 2975 WEST 2100 SOUTH SALT LAKE CITY, UT

US 84119

Contact: TONY PAYAN tpayan@arnoldmachinery.com

T: (801)972-4000 F: (801)975-9434

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8770Unique No:11036056Signed:Sean FeltonReport Date:22 May 2024

233

145

246

547

0

12



CONSTRUCTION EQUIPMENT





