



CONSTRUCTION EQUIPMENT

549962 VOLVO L220H 3382 - TRANSMISSION (AUTO)



Sample No: VCP454881
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 549962



SAMPLE INFORMATION

Sample Number	VCP454881	---	---	---
Sample Date	11 May 2024	---	---	---
Machine Hours	6129	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

COVANTA
 350 FLAKENBURG ROAD
 TAMPA, FL
 US 33619
 Contact: SERVICE MANAGER



OIL CONDITION

Visc @ 40°C	cSt	█ 27.4	---	---	---
-------------	-----	--------	-----	-----	-----

T: (813)684-5688
 F:



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 3	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 88	---	---	---
Copper	ppm	█ 24	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ 3	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 6	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 80	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 28	---	---	---
Phosphorus	ppm	█ 175	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 60	---	---	---

Depot: COVTAM
Unique No: 11036109
Signed: Wes Davis
Report Date: 21 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

