CONSTRUCTION EQUIPMENT RSO-038028 HITACHI 060320 - COOLANT



Sample No:VCP447619Oil Type:{unknown}Job No:RSO-038028

VOLVO

SAMPLE IN	IFORMATION				
Sample Number	-	VCP447619			
Sample Date		10 May 2024			
Machine Hours		270			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.79			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	676			
Percentage Glycol	%	50.6			
Freezing Point	°C	-35			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Green			



SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com T: (205)943-2268 F: (205)943-2269

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SAIBIRUnique No:11036196Signed:Jonathan HesterReport Date:24 May 2024Contact/Location: STEPHANI BRITTON - SAIBIR

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

