



CONSTRUCTION EQUIPMENT

549962 VOLVO L220H 3382 - COOLANT



Sample No: VCP439148
Oil Type: VOLVO RED
Job No: 549962



SAMPLE INFORMATION

Sample Number	VCP439148	---	---	---
Sample Date	11 May 2024	---	---	---
Machine Hours	6129	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.95	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 48.7	---	---	---
Freezing Point	°C	■ -31	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---



COVANTA
 350 FLAKENBURG ROAD
 TAMPA, FL
 US 33619
 Contact: SERVICE MANAGER

T: (813)684-5688
 F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: COVTAM
Unique No: 11036206
Signed: Jonathan Hester
Report Date: 24 May 2024




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

